

- 4 NEVER place tools on painted surfaces, seating surfaces, dash pad, console or floor carpet/mats.
- 5 Always wear appropriate personal protective equipment, including gloves, safety glasses, etc., when required.
- 6 Record radio presets prior to disconnecting battery power, if needed.
- Ensure the transportation fuse is set to "ON" before starting the install. 7
- 8 Roll down the driver's window and adjust the power seats (if applicable) prior to disconnecting battery power, if needed.
- 9 To perform this installation, BOTH Smart Keys MUST be available.
- 10 The following instructions are for the GDS Mobile (GDSM) Scan tool. Instructions for GDS Laptop are similar.









10	GDSM Device	11 GDSM Device
	GENESISCHI/2015/G 5.0 GDI VCI DX     S/W Management III     Smart Key Code Saving     • I Smart Key code saving ]     • [ Condition ]     1, IG Off     Please have FOB key to teach and press [OK] button.	GENESIS(DH)/2015/G 5.0 GDI VCI C C     S(W Management III     Smart Key Code Saving      •[Smart Key code saving]     Status LEARNT     Input PIN code and press [OK] button.
	Cancel OK Cancel Units function.	Exter the unbiging NEW DIN and found in Stop 18. Select the "DONE"
N O T E	Turn the venicle ignition to "OF" (Key OF", Engine OFF).     Before proceeding, ensure that you have the <u>two (2) Smart Key</u> <u>Fobs</u> and <u>one (1) Card Key</u> within reach.     Select "OK".	N - If the New PIN Code fails, reattempt using the Old PIN Code. 2. Select *OK*. T
12	GDSM Device	13 GDSM Device
	Control C	
12 N O T E	GDSM Device      Centers(SQDH)/2015/6 5.0 GD     VC CC     S/W Management     S/W Management     Smart Key Code Saving      (Smart Key code saving ]     Ist key teaching.     (LSt, and then press SSB(Start Stop Button) using 1st FOB within 5     seconds.     (Do not use your finger to press SSB, but use FOB itself)     Continue? (OK/Cancel)      (OK/Cancel)      (Add one (1) of the vehicle's original smart keys in your hand. 2. Select "OK".	13       Image: CDSM Device         Image: CDSM Device       Image: CDSM Device         Image: CDSM Device



Visual Check					
Item to be Checked		Result			
	Removed panels are all replaced.	Fuse Cover Panel has been re-installed.			
	Card Key is attached to the key ring with both Smart Key Fobs and are stored in the center console cup holder.	All Keys are attached together and stored in the center console cup holder.			
$\checkmark$	User Manual has been placed in the Glove Box.	User Manual is in the Glove Box.			
Function C	heck				
	Item to be Checked	Result			
	Exit the vehicle, Place the two (2) smart keys on a table more than 5m (15ft) away, Return to the vehicle with the Card Key in hand, Lock the doors with the button on the Driver's Door Handle, Move to the trunk, Open the trunk by pressing the switch pad, Close the trunk, Move to the Driver's door, Unlock the door with the switch on the Driver's Door Handle, Enter the vehicle, Start the vehicle, Stop the vehicle.	The doors will lock. The trunk will open. The driver door will unlock. The vehicle will start. The vehicle will stop running.			
	Place the Card Key and Smart Key #2 more than 5m (15ft) away. Retrieve Smart Key #1, check that the LOCK/UNLOCK buttons work properly and Smart Key #1 is able to turn on/turn off the engine.	Driver door will lock & unlock according to the fob button pressed. All doors will unlock, if the UNLOCK button is double-pressed, according to the vehicle settings. Vehicle will start and stop the engine.			
	Place the Card Key and Smart Key #1 more than 5m (15ft) away. Retrieve Smart Key #2, check that the LOCK/UNLOCK buttons work properly and Smart Key #2 is able to turn on/turn off the engine.	Driver door will lock & unlock according to the fob button pressed. All doors will unlock, if the UNLOCK button is double-pressed, according to the vehicle settings. Vehicle will start and stop the engine.			
	Check to see if the mechanical key from Card Key will easily LOCK/UNLOCK the driver's door.	Door should lock and unlock without excessive force or binding.			

#### Troubleshooting

Issue / Concern		Items to be Checked	
	Pairing process cannot be completed (any key).	Confirm OBDII Wireless Transceiver is properly attached. Confirm GDS Device is sync'd with the Transceiver. Confirm GDS Device has recognized the correct vehicle & model year. Ensure all low frequency electronics are removed from the vehicle, including cell phones. Ensure when pairing, you are pressing and holding the Start Stop Button with the Smart Key until it is successful.	
	Pairing process cannot be completed (Card Key).	Card Key may have been paired with another vehicle. Ensure when pairing, you are pressing and holding the Start Stop Button with the Card Key's indicated corner (Upper Left).	
$\checkmark$	Intermittent malfunction of Card Key.	Ensure that Card Key is not placed near cell phone or other electronics. Check for fully or partially discharged battery in Card Key.	