
MMC has eliminated the front air guide panels (LH/RH) on Lancers without "factory fitted Fog lamps".

When you install the "Accessory Fog lamp kit" for this vehicle (which did not come equipped the "Air guide panel,LH/RH),

please get 2pcs of "Harness Clamp - MS470067 to hold the "Fog lamp harness" instead of "white resin harness clip" as shown below.


The following pictures show only the "LH side" of the grille. Please work the "RH side" as same manner.

Present situation and fixing procedure



The "Air guide panel,LH/RH will be deleted. So, it can not use the fixing point [*].

The fixing point [*]





Future situation and fixing procedure


Please fix the "Harness clamp" together with the "screw for radiator grille.

It can be use for the current vehicles which equipped with "Air guide panel.









Note) The new Fog lamp kit will be available which including "2pcs of harness clamps" and also "3pcs of white resin harness clips".